Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/Client 50005DE8448/1

Work Order Type: Weatherization Audit Name: Audit DE8448

CLIENT INFORMATION

Client Name: Address:

Client ID: Client 50005DE8448

Alt. Client ID:

AGENCY INFORMATION

Agency: 50005DE **Agency Phone:** (901) 476-5226

Address: P. O. BOX 634, 915 HWY 51 SOUTH **Fax:** (901) 476-5258

Agency Contact: Treadwell, Dwight Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Measures

Comment	pair 2' x 2' hole in bathro	om floor		Component	ts		- 1	nspecte	
			Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
10 Unspecified	Misc Material	Each	1						
Other Detail									
			Measur	e Sub Total:] .	Sub Total:		
Field Notes:									
Measure 2 Re	palce broken panes in W	71, W5		Componen	ts			nspecte	
	palce broken panes in W	71, W5		•				nspecte	
Measure 2 Re	palce broken panes in W Description / Comment	/1, W5	Qty	Componen: Estimated Unit Cost		Qty	Actual Unit Cost	nspecte	
Measure 2 Re Comment # Material / Labor	•		Qty 1	Estimated		Qty	Actual		
Measure 2 Re Comment # Material / Labor 0 Unspecified	Description / Comment	Units	_	Estimated		Qty	Actual		
Measure 2 Re Comment # Material / Labor	Description / Comment	Units	_	Estimated		Qty	Actual		
Measure 2 Re Comment # Material / Labor 0 Unspecified	Description / Comment	Units	_	Estimated		Qty	Actual		

Report Run On: 5/23/2010

Measure 3 Infi	iltration Redctn			Componen	its			Inspected
1.Insul 2. Cau 3. Cau 4. Add 5. Rep 6. Air s	FILTRATION MEASURES ate attiic door lk Front door lk windows 1-6 inside and threshold side door air facing side door seal plumbing penetrations k and seal AC wall unit	out						
# #				Estimated		Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Measure 4 DW	/H Pipe Insulation			Componer	ıts			Inspected
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								

Inspected

Measure 5 Inst	all/Replace Heatpump			Componen		ers,Wind	dow AC	Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Heating Equipment	Heatpump - 8 kBtu/h Existing, Consult Manual J Data	Each	1					
2 Labor	Heatpump - 8 kBtu/h Existing, Consult Manual J Data	Each	1					
Other Detail								
			Moseur	e Sub Total:]	Sub Total:	
Field Notes:			Measur	e Sub Total.				
	rigerator Rplcmnt			Componen	ts			Inspected
Comment				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Refrigerators	-	Each	1					
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:				L			L	

Report Run On: 5/23/2010

Measure 7 CO Monitor is Needed					Componen		Inspected		
C	Comment								
			Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail						,		
			Measur	e Sub Total:] ;	Sub Total:		
	Field Notes:								
ļ									
			Work O	rder Gra	and Total:		Gran	d Total:	